

Perkins 1006 engine, fire damaged



PRODUCT NO.: 17286

Serial no.: YB50328U536762U

Location: 5B

Condition: Used

Brand: Perkins

Description

ex Komatsu PC240-5 s/n K20490. Fuelpump defect (fire) - generator and starter missing - turns OK.
SOLD: Oil sump with suction pipe and oil dipstick, inlet and exhaust manifold

Gallery



