

Repair kit for Komatsu engine S6D 105-1



PRODUCT NO.: 6398

Condition: Used

Brand: Komatsu

Description

Consists of: 6 pistons 6137-32-2110 and 6 liners 6137-22-221 and 6 bearingset 6138-31-3040

Gallery

